



Section	~b	~h	
mm			
mm			
28x14	28	14	
30x14	30	14	
32x14	32	14	
33x14	33	14	
34,5x14	34,5	14	

Orders as per length La.

<b>28x14</b>		
La		
mm		1120
<b>34,5x14</b>		
La		
mm		1120
<b>30x14</b>		
La		
mm		1120
<b>32x14</b>		
La		
mm		1120
<b>33x14</b>		
La		
mm		1120

- Belts are resistant to temperatures from -45 °C to +80 °C.
- Increased resistance to mineral oils.
- Increased resistance to abrasion.

Example of marking: □□ **28x14 1120 La**

28x14 - marking of section

La - inside length