

		1230	
	1235		
1301			1309
		1372	
	1375		
1380			

PK			
Le mm			
		630	
		650	
	698		
700			736
		737	
	740		742
		800	
	812		
847			850
		853	
	950		954
		968	
	970		
975			980
		985	

PK			
Le mm			
	1005		
1015			1045
		1050	
	1054		
1060			1070
		1150	
	1152		
1163			1165
		1170	
	1180		
1220			1225
		1230	
	1300		
1365			
1370			

Belts are resistant to temperatures from -45 °C to +80 °C.
Increased resistance to mineral oils.
Increased resistance to abrasion.

Example of

marking: **4PK 954**
4 - number of ribs
PK - marking of section
954 - effective length