

```
<table border="0" width="550"><tr><td rowspan="1"> </td><td rowspan="1"> </td><td scope="" style="width: 450px;" dir="" id="" align="" valign="" lang=""> </td><td align="right"> <br /></td></tr><tr><td scope="" style="" dir="" id="" rowspan="1" align="left" valign="top" lang=""> <br /></td><td scope="" style="" dir="" id="" rowspan="1" align="left" valign="top" lang=""><table bordercolorlight="#99b7d1" bordercolordark="#ffffff" align="center" bgcolor="#ffffff" border="1" cellpadding="2" cellspacing="0" width="140"><tr><td>Section</td> <td>~b<br />mm</td> <td>~h<br />mm</td> </tr> <tr> <td>HB</td> <td>16,5</td> <td>15</td></tr></table><br />Orders as per length Lw. <br /></td><td scope="" style="" dir="" id="" align="left" valign="top" lang=""><table bordercolorlight="#99b7d1" bordercolordark="#ffffff" align="center" bgcolor="#ffffff" border="1" cellpadding="2" cellspacing="0" width="200"><tr><td>Section</td> <td>Range of Lw lengths</td> </tr> <tr> <td>2-HB</td> <td>2240 - 5000</td> </tr> <tr> <td>2-HB Ravlek</td> <td>1400 - 12500</td> </tr> <tr> <td>3-HB</td> <td>1400 - 9300</td> </tr> <tr> <td>3-HB Ravlek</td> <td>1400 - 12500</td> </tr> <tr> <td>4-HB</td> <td>1400 - 9300</td> </tr> <tr> <td>4-HB Ravlek</td> <td>1400 - 12500</td> </tr> <tr> <td>5-HB</td> <td>1400 - 9300</td> </tr> <tr> <td>5-HB Ravlek</td> <td>1400 - 12500</td> </tr> <tr> <td>6-HB</td> <td>1400 - 12500</td> </tr> <tr> <td>6-HB Ravlek</td> <td>1400 - 12500</td></tr></table></td><td colspan="1"> </td><td colspan="1"> </td><td colspan="1"> </td></tr><tr><td colspan="1" rowspan="1" colspan="4"> The listed lengths are only recommended. Any length is available in the mentioned range.</td></tr><tr><td colspan="1"> </td><td colspan="1"> </td><td colspan="1"> </td><td colspan="1"> </td></tr><tr><td colspan="1" rowspan="1" colspan="1" style="" dir="" id="" colspan="1" align="center" valign="top" lang=""><table bordercolorlight="#99b7d1" bordercolordark="#ffffff" align="center" bgcolor="#ffffff" border="1" cellpadding="2" cellspacing="0" width="100"><tr><td class="HEAD"><b>HL</b></td> </tr> <tr align="center"> <td class="HEAD" width="100"><b>Lw<br />mm</b></td> </tr> <tr> <td>1400</td> </tr> <tr> <td>1450</td> </tr> <tr> <td>1500</td> </tr> <tr> <td>1550</td> </tr> <tr> <td>1600</td> </tr> <tr> <td>1650</td> </tr> <tr> <td>1700</td> </tr> <tr> <td>1750</td> </tr> <tr> <td>1800</td> </tr> <tr> <td>1850</td> </tr> <tr> <td>1900</td> </tr> <tr> <td>1950</td> </tr> <tr> <td>2000</td> </tr> <tr> <td>2060</td> </tr> <tr> <td>2120</td> </tr> <tr> <td>2180</td> </tr> <tr> <td>2240</td> </tr> <tr> <td>2300</td> </tr> <tr> <td>2360</td> </tr> <tr> <td>2430</td>
```

		2500																																																																									
<table border="1"> <thead> <tr> <th colspan="4">HL</th> </tr> <tr> <th>Lw</th> <th></th> <th></th> <th></th> </tr> </thead> <tbody> <tr> <td>2650</td> <td>2580</td> <td></td> <td></td> </tr> <tr> <td>2720</td> <td></td> <td>2800</td> <td></td> </tr> <tr> <td></td> <td></td> <td>2900</td> <td></td> </tr> <tr> <td></td> <td>3000</td> <td></td> <td></td> </tr> <tr> <td>3070</td> <td></td> <td></td> <td>3150</td> </tr> <tr> <td></td> <td></td> <td>3250</td> <td></td> </tr> <tr> <td></td> <td>3350</td> <td></td> <td></td> </tr> <tr> <td>3450</td> <td></td> <td></td> <td></td> </tr> <tr> <td>3550</td> <td></td> <td></td> <td>3650</td> </tr> <tr> <td></td> <td></td> <td>3750</td> <td></td> </tr> <tr> <td></td> <td>3870</td> <td></td> <td></td> </tr> <tr> <td>4000</td> <td></td> <td></td> <td>4120</td> </tr> <tr> <td></td> <td></td> <td>4250</td> <td></td> </tr> <tr> <td></td> <td>4370</td> <td></td> <td></td> </tr> <tr> <td>4500</td> <td></td> <td></td> <td></td> </tr> <tr> <td>4620</td> <td></td> <td></td> <td></td> </tr> </tbody> </table>				HL				Lw				2650	2580			2720		2800				2900			3000			3070			3150			3250			3350			3450				3550			3650			3750			3870			4000			4120			4250			4370			4500				4620			
HL																																																																											
Lw																																																																											
2650	2580																																																																										
2720		2800																																																																									
		2900																																																																									
	3000																																																																										
3070			3150																																																																								
		3250																																																																									
	3350																																																																										
3450																																																																											
3550			3650																																																																								
		3750																																																																									
	3870																																																																										
4000			4120																																																																								
		4250																																																																									
	4370																																																																										
4500																																																																											
4620																																																																											
<table border="1"> <thead> <tr> <th colspan="4">HL</th> </tr> <tr> <th>Lw</th> <th></th> <th></th> <th></th> </tr> </thead> <tbody> <tr> <td>4750</td> <td></td> <td></td> <td>4870</td> </tr> <tr> <td></td> <td></td> <td>5000</td> <td></td> </tr> <tr> <td></td> <td>5150</td> <td></td> <td></td> </tr> <tr> <td>5300</td> <td></td> <td></td> <td>5450</td> </tr> <tr> <td></td> <td></td> <td>5600</td> <td></td> </tr> <tr> <td></td> <td>5800</td> <td></td> <td></td> </tr> <tr> <td>6000</td> <td></td> <td></td> <td></td> </tr> <tr> <td>6150</td> <td></td> <td></td> <td>6300</td> </tr> <tr> <td></td> <td></td> <td>6500</td> <td></td> </tr> <tr> <td></td> <td>6700</td> <td></td> <td></td> </tr> <tr> <td>6900</td> <td></td> <td></td> <td>7100</td> </tr> <tr> <td></td> <td></td> <td>7300</td> <td></td> </tr> <tr> <td></td> <td>7500</td> <td></td> <td></td> </tr> <tr> <td>7750</td> <td></td> <td></td> <td></td> </tr> <tr> <td>8000</td> <td></td> <td></td> <td>9300</td> </tr> <tr> <td></td> <td></td> <td>12500</td> <td></td> </tr> </tbody> </table>				HL				Lw				4750			4870			5000			5150			5300			5450			5600			5800			6000				6150			6300			6500			6700			6900			7100			7300			7500			7750				8000			9300			12500	
HL																																																																											
Lw																																																																											
4750			4870																																																																								
		5000																																																																									
	5150																																																																										
5300			5450																																																																								
		5600																																																																									
	5800																																																																										
6000																																																																											
6150			6300																																																																								
		6500																																																																									
	6700																																																																										
6900			7100																																																																								
		7300																																																																									
	7500																																																																										
7750																																																																											
8000			9300																																																																								
		12500																																																																									
<p>Lw = La</p> <p>Li = La - 62</p> <p>Belts are resistant to temperatures from -30 °C to +60 °C at</p>																																																																											

relative humidity 65+/-15%.</td></tr><tr><td colspan="4"><hr size="2"  
width="100%"></td></tr><tr align="center"><td colspan="4"> Example of marking:<b> 3HB  
2800 Lw</b><br /><br />3HB - number of ribs and marking of section<br />Lw - pitch  
length</td></tr></table>