



Section	~b		
mm	~h		
mm			
HH	20	10	
HL	45	20	
HM	50	22	

Orders as per length Lw.

HH	Lw	
mm		1150
HL	Lw	
mm		1713
		1769
		2134
HM	Lw	
mm		2132

Belts are resistant to temperatures from -45 °C to +80 °C.
 Increased resistance to mineral oils.
 Increased resistance to abrasion.

Example of marking:

HL 1713 Lw / 45x20x1630 Li AGRO SUPER

HL - marking of section

Lw - pitch length

AGRO SUPER - agricultural raw edge V-belt.